


Prevent Water Intrusion at Windows  
(Stucco Clad Buildings)

Save Time and Money with this Method



1. PROBLEM - Wind driven rain can enter here (between window and stucco)

2. SOLUTION - Repair by:


a. Small saw kerf ( $\frac{1}{8}$ " wide or less x  $\frac{1}{2}$ " deep) at juncture of frame & stucco

b. Install Adeka Ultraseal® 4mm string

c. Seal joint with Dow Corning Silicone long term flexible sealant

3. This procedure developed and recommended by:

**John J. Bucholtz, PE**  
**Construction Quality Engineers, Inc.**



Adeka Ultraseal® KM 4mm

Sealant

Detail and procedure as outlined in Mr. Bucholtz's "Techniques and Comments" newsletter number 191

**OCM, Inc.**

1120 Peterson Road, Grayslake, IL 60030

Toll Free: 866-457-5710 • Phone: 847-462-4258 • FAX: 847-462-4259

www.adeka.com • www.ocm-inc.com • sales@ocm-inc.com