

# OCM OSHA REBAR CAP

## Installation Guide/Specification Sheet



### Model #REBARCAP-38OSHA



#### INSTALLATION:

- OCM OSHA Rebar Caps are to be inspected before each use for damage. Damaged units should not be used.
- There should be no damage to the cap or the fins that contact the exposed rebar ends. If damage such as general cracking or damaged fins is observed please discard the cap. If the fins inside are damaged it will cause the cap to not fit tightly on the end of the protruding rebar and therefore will affect the ability of this cap to function properly. This could cause serious injury or impalement if a damaged cap is used.
- Place the OCM OSHA Rebar Cap firmly on to the end of the protruding rebar.
- Push firmly until the OCM OSHA Rebar Cap's internal metal insert comes into contact with the end of the protruding rebar.
- OCM OSHA Rebar Cap must be centered vertically on protruding rebar end in order to secure a tight fit.
- Please check that the cap is secured properly on the rebar such that the top surface of the cap is set in a perpendicular manner to the vertical exposed rebar end.

#### WARNINGS:

- Protective covers, like the OCM OSHA Rebar Cap, must be fully and properly installed on rebar. Protective covers are designed for use only at grade or above grade.
- The OCM Model #REBARCAP-38OSHA (OCM OSHA Rebar Cap) is designed to protect against the hazard of impalement for a maximum fall height not to exceed 7-1/2 feet from the top of the cap.
- Federal OSHA limits the use of protective cover to fall heights of not more than 6 feet. California OSHA limits the use of protective cover to fall heights of not more than 7-1/2 feet..
- Proper use of this product is the responsibility of the user. User must be familiar with all appropriate codes and regulations.
- OCM OSHA Rebar Caps are limited for use with #3 - #8 rebar only.

#### SPECIFICATIONS:

- Safety Orange Color with High Impact Plastic.
- Material Fits Rebar Sizes #3 - #8.
- 4" X 4" Square Design with internal metal insert.
- Packed in boxes of 100 pcs per box.

OCM, Inc.

1120 Peterson Road, Grayslake, IL 60030

Toll Free: 866-457-5710 • Phone: 847-462-4258 • FAX: 847-462-4259

www.ocm-inc.com • sales@ocm-inc.com