



PL50-7.25

OCM, Inc's Ply Lags are used to fasten wales or strongbacks. They can also be used internally to fix coil ties (etc.) to the form.

Part Number	PL50-7.25
Safe Working Load (lbs)	3,000
D Size (in)	1/2"
L Length (in)	4-1/2"
Overall Length (in)	7-1/4"